




HYDRAULIC LINE WIPERS

PARVEEN Hydraulic Line Wipers are used to remove excess grease from braided cable when retrieving tools from the well. Line wipers are supplied with quick union or tubing connections at bottom.



**HYDRAULIC
LINE WIPER**


HYDRAULIC LINE WIPERS		
Working Pressure (PSI)	Service	Part No.
3,000	H2S	210-35XX
5,000	H2S	210-55XX

*Please specify cable size when ordering.

*Refer to the Quick Union identification chart on page no. 16 & 17 for end connections.

CHECK VALVE UNIONS

PARVEEN Check Valve Unions are designed to seal off well pressure in the event of the wireline parting from the tool string. The steel ball is forced against the metal sealing area by the well pressure from below. The check valve unions are manufactured as one piece body and are assembled below the stuffing box or grease injection control head. The internal check valve assembly can also be fitted as an integral part of the stuffing box or grease injection control head. This helps to reduce the height of lubricator assembly.



**CHECK VALVE
UNION**

CHECK VALVE UNIONS		
Working Pressure (PSI)	Service	Part No.
5,000	H2S	09-1254-XX
10,000	H2S	09-1214-XX

*Please specify wire/cable size when ordering.

*Refer to the Quick Union identification chart on page no. 16 & 17 for end connections.